

Machine List-Plant 4

Cutting

❖ 2D Laser Fiber Cutting 3000 W	1
❖ Laser Cutting 4000 W	1
❖ Plasma Cutting 400 A	1
❖ Semi Automatic Band Saw	1

Bending

❖ Press Brake 90 T	1
❖ Press Brake 100 T	1
❖ Press Brake 300 T	1
❖ Press Brake 400 T	1

Welding

❖ CO2 Welding 500 A	5
❖ CO2 Welding 350A	15
❖ 6-Axis Arc Weld Robot (FD-B4L)	5
❖ Welding Positioner	4
❖ Hydraulic Flash Butt Welding	2